ECS Configuration Change Request					Page 1 of	f Par	ge(s)	
1. Originator	2. Log Date:	3. CCR #:	4	. Rev:	5. Tel:	6. Rm #:	7. Dept.	
Maryellen Corbett	8 AUG 00	00-01	810		0703	2072C	SE COTS	
8. CCR Title: SGI FLEXIm License Server Baseline Change								
9. Originator Signature/Date 10.				ss	11. Type:	12. Need Date	: 09/01/2000	
Maryellan Corbett 8/8/2000			工	II CCR				
13. Office Manager Signature/Date				ategory of Change: 15. Priority: (If "Emergency"				
16. Documentation/Drawings Impacted:				_	seline Doc.	fill in Block 28). Routine		
16. Documentation/Drawings Impacted: 920-TDE-002, 920-TDL-002, 920-TDV-003, 920-TDG-003, 920-TDL-003, 920-TDN-003 17. Schedule Impact: 18. Cl(s) Affected:								
19. Release Affected by this	Change:	20. Date due t	to Custom	er: 2	21. Estimated C	ost:	. .	
5B					None - Under 100K			
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:								
Updates are needed to the SGI FLEXIm License server host baseline information at LARC/EDC. Some impacts have occurred or will occur because of hardware movement. The attached red-lined updates will identify the 3 SGI FLEXIm servers at LARC, EDC that have been impacted or will be impacted by HW moves.								
24. Proposed Solution: (use additional sheets if necessary) At EDC, e0aqg02, e0spg05 and e0wkg01 will be the 3 SGI FLEXIm redundant license servers after IRIX 6.5 transition upgrade (Release 55). LARC has currently baselined l0drg01 and l0drg03 as SGI FLEXIm license servers. l0acg01 is added as the third SGI FLEXIm license server, so that 3 SGI FLEXIm license servers will be available to configure in the baselined redundant server license configuration. Red-lines for the appropriate baseline documents are attached, including a new VATC and NSIDC version of 920-TDx-003. 25. Alternate Solution: (use additional sheets if necessary) ldentify alternative SGI FLEXIm servers.								
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inability to configure 3 SGI FLEXIm servers in the baselined redundant mode configuration for SGI license access failover.								
27. Justification for Emergency (If Block 15 is "Emergency"):								
28. Site(s) Affected: DEDF XPVC DVATC DEDC SGSFC DLARC NSIDC DSMC DAK DPL								
29. Board Comments:	O	Culei		30. Wo	ork Assigned To	: 31. CCR C	osed Date:	
					, , , , , , , , , , , , , , , , , , ,		J. 100,	
32. EDF/SCDV CGB Chair (S		isposition: Ap	proved A	op/Com	. Disapproved	Withdraw Fwd	/ESDIS ERB	
	110100	Fw	d/ECS					
33. M&O CCB Chair (Sign/Da	D D	isposition: App		p/Com	. Disapproved	Withdraw Fwd	ESDIS ERB	
While	15 Aug 00	FW	d/ECS					
34. ECS CCB Chair (Sign/Da	te): Ois	sposition: App	roved App	p/Com.	Disapproved	Withdraw Fwo	/ESDIS ERB	

ORIGINAL

CM01JA00

ECS/EDF/SCDV/M&O